



| Pin | Colour | Function* |
|-----|-------------------|-----------|
| 1 | brown | A/STP0 + |
| 2 | brown/white | A/STP0 - |
| 3 | red | B/DIR0 + |
| 4 | red/black | B/DIR0 - |
| 5 | orange | A/STP1 + |
| 6 | orange/black | A/STP1- |
| 7 | yellow | B/DIR1+ |
| 8 | yellow/black | B/DIR1 - |
| 9 | green | A/STP2 + |
| 10 | green/black | A/STP2 - |
| 11 | blue | B/DIR2 + |
| 12 | blue/white | B/DIR2- |
| 13 | purple | WDOG - |
| 14 | grey | Z/ENO + |
| 15 | grey/black | Z/ENO - |
| 16 | white | 5V Out |
| 17 | white/black | 0V |
| 18 | pink | Z/ENB1 + |
| 19 | pink/black | Z/ENB1 - |
| 20 | pale blue | 5V Out |
| 21 | light blue/black | 0V |
| 22 | light green | Z/ENB2 + |
| 23 | light green/black | Z/ENB2 - |
| 24 | white/red | 5V Out |
| 25 | white/blue | 0V |
| 26 | purple/white | WDOG + |

* Function dependant on Axis Type.



QUICK START GUIDE MDR CABLE (FLEXSLICE)

Strip the non connector end of the cable to form flying leads and wire as required



UK | USA | CHINA | INDIA
WWW.TRIOMOTION.COM
THE MOTION SPECIALIST

CAD data Drawings to aid packaging and mounting are available in various formats from the Trio web site. Products should be wired by qualified persons.
Specifications may change without notice. E & OE

Quick Start v2 December 2017